

# Feldman Production Services

## Cable/Distro

### Electric Cables:

6 50' 4 wire type w banded mole pin cable w/ reverse ground  
6 50' 100 amp Bates extensions  
7 50' 60 amp Bates extensions  
4 25' 60 amp Bates extensions

### Distribution:

3 400 amp pin through boxes (4 100 amp bates w/ circuit breakers)  
1 800 amp pin through box  
2 sets of 5 piece 3fers  
1 5 piece lug adapter  
10 2ot jumpers  
2 male to male  
2 female to female  
4 snake bite  
10 80amp 4 way gang to Bates w/ breakers

### Splitters:

5 100 ampt to 2 100 amp 2fers  
9 100 amp to 2 60 amp Bates  
5 60 amp 4 way gang to Bates

### Grounding system:

4 50' green ground pin to pin  
1 50' green ground male pin to clip  
4 18" grounding spiders: 1 female to 5 male  
2 36" grounding spiders: 1 female to 5 male

### Stingers:

15 25' 12/3 stingers  
15 50' 12/3 stingers  
2 4way edison to edison